

Widespread corrosion at the Richmond Refinery

This page: The pipe that ruptured in Chevron's disastrous August 2012 fire (point 1 below) is just one of at least twenty known places where corrosion damaged equipment in its crude unit alone.

Next page: Corrosion attacks process equipment refinery-wide.

1. #4 sidecut pipe from atmospheric column C-1100 to pumps P-1149/A: sulfidation corrosion leads to rupture in Aug. 2012 fire

5. Atmospheric reflux drum V-1100 shell: internal corrosion

8. Relief piping for atmospheric reflux drum V-1100: 43% of pipe wall is lost to external crevice corrosion

10. #7 sidecut pipe from pumps P-1179 & 1189A to exchanger E-1109: sulfidation corrosion repairs

11. Atm. overhead pipe from E-1101 to condenser: external corrosion pitting

12. Atm. overhead pipe from E-1100 to V-1100: extensive internal corrosion pitting, found after fire-damaged pipe removed, suggests a failure risk before the next scheduled shutdown

13. FT-007 tubing between reflux drum V-1100 & exchanger E-1100: corrosion at compression fitting

15. Reflux drum V-1100 pH sample pipe & tubing: repeated plugging suggests corrosion upstream

17. Aqueous ammonia tank TK-1108: underside & internal corrosion

18. Atm. overhead pipe from C-1100 to E-1101: external corrosion, bulging & delamination

20. Condensate pipe adjacent to C-1100 & pumps P-1105/A: corrosion under insulation

2. Atmospheric overhead pipe from C-1100 to relief header: extensive internal corrosion pitting, found after fire-damaged pipe was removed, suggests a failure risk before the next scheduled maintenance shutdown

6. Condensate pipe downstream from vessel V-1164: internal & external corrosion & leaks

3. Atmospheric column C-1100 shell: corrosion under insulation

4. Atmospheric column C-1100 pressure taps PT 001 & 003: internal pitting corrosion



7. C-1100 crude feed pipe from furnaces F-1100A/B: internal weld corrosion after repair from naphthenic acid corrosion

9. Smothering steam piping for furnace F-1160 firebox: localized corrosion found since 2006

14. Stripping steam pipe to atm. column C-1100: corroded & leaking

16. Stripping steam piping to column C-1130: corrosion under insulation thins pipe to 50% of recommended replacement thickness

19. Medium-pressure condensate header piping: corrosion under insulation



The small red box in this map of Richmond refinery processing areas shows the crude unit areas in the detailed blow-up above.

Continued next page...

Widespread corrosion at the Richmond Refinery

page two

The extensive corrosion documented above represents only a partial sample in a small part of the refinery. Chevron reported those data publicly only for crude unit equipment it sought permits to replace or repair after its August 2012 fire (1–20). And some serious corrosion damage was found only after fire-damaged equipment was dismantled and easier to inspect (e.g., 2, 12).

Corrosive chemicals—such as hydrogen sulfide formed in high-temperature processing of oil feedstock that is contaminated by sulfur—can attack processing equipment refinery-wide.

Workers “downstream” from the Richmond crude unit warned in 2011 that Chevron was ignoring widespread and accelerating corrosion following its switch to higher sulfur crude oils (21). At the Richmond lube oil processing area alone (see the black rectangle in the map above), the refinery workers identified at least seven examples of corrosion-damaged equipment:

- Accelerating internal corrosion of the V-1410 High Pressure Separator process vessel;
- Internal corrosion damage of the Column C-1500 process vessel and trays;
- Corrosion and cracking of the Column C-1500 impingement plate and cladding;
- Plugging of the Column C-1500 sidecuts by corrosion products (“scale”);
- Corrosion damage in Vessel V-1110, which is upstream of Column C-1200;
- Plugging of the Column C-1200 reboilers by corrosion products (scale); and
- A corroded furnace tube elbow failed in a fire at Heavy Neutral Cracker Furnace F-1551 (21).

Refiners can install clamps on corroded pipes to stop leaks as a temporary stop-gap measure. Reported data on this practice at Richmond reveals a refinery-wide corrosion problem:

- Refinery-wide, Chevron relied on as many as 2,000 of these temporary clamps in 2012 (22).
- Cal-OSHA inspected a portion of these temporary clamps and cited Chevron for relying on at least nine of these clamps long after the corroded equipment should have been replaced (23).

Ignoring worsening corrosion greatly increases catastrophic incident risk refinery-wide.

References for points of corrosion damage in the Richmond refinery Crude Unit:

(1) Chevron, 2012. Tracking–Additional Work (TAW) 17531, City of Richmond Permit 12-05068 sub 12-05740. (2) Chevron 2012. TAW 18111, City Permit 12-05068 sub 12-05383. (3) Chevron, 2012. TAW 17933, City Permit 12-05068 sub 12-05069. (4) Chevron, 2012. TAW 18437, City Permit 12-05068 sub 12-05740. (5) Chevron, 2012. TAW 17881, City Permit 12-05068 sub 12-05072. (6) Chevron, 2012. TAW 18467, City Permit 12-05068 sub 12-05596. (7) Chevron, 2012. TAW 17568, City Permit 12-05068 sub 12-05069. (8) Chevron, 2012. TAW 18410, City Permit 12-05068 sub 12-05491. (9) Chevron, 2012. TAW 18067, City Permit 12-05068 sub 12-05493. (10) Chevron, 2012. TAW 18606, City Permit 12-05068 sub 13-00079. (11) Chevron, 2012. TAW 18206, City Permit 12-05068 sub 12-05385. (12) Chevron, 2012. TAW 18096, City Permit 12-05068 sub 12-05153. (13) Chevron, 2012. TAW 17916, City Permit 12-05068 sub 12-05153. (14) Chevron, 2012. TAW 17594, City Permit 12-05068 sub 12-05486. (15) Chevron, 2012. TAW 17737, City Permit 12-05068 sub 12-05689. (16) Chevron, 2012. TAW 18238, City Permit 12-05068 sub 12-05600. (17) Chevron, 2012. TAW 17910, City Permit 12-05068 sub 12-05490. (18) Chevron, 2012. TAW 18149, City Permit 12-05068 sub 12-05489. (19) Chevron, 2012. TAW 18068, City Permit 12-05068 sub 12-05493. (20) Chevron, 2012. TAW 17845, City Permit 12-05068 sub 12-05596.

Reference for points of corrosion damage in the Richmond refinery Lube Processing Area:

(21) Cal-OSHA, 2012. Inspection report, Inspection 314328980 (unsafe working conditions complaint).

References for clamps on corroded piping at Richmond refinery-wide:

(22) Garrett Brown, Senior Safety Engineer & Special Assistant to the Chief, Cal-OSHA, personal communication with Greg Karras, CBE, on 31 January 2013. (23) Cal-OSHA, 2013. Inspection 314332370 (Citation 8 Item 1).